







SONGESAND



Design and Quality
IKEA of Sweden




1



101356

8x



153507


2x



119253
118137


2x

2




101356

6x




153507

6x



110630

14x



153548
158568


2x

3




114671

8x




118331

2x



110789

16x



105163

4x




110630

2x




117327

3x




101359

8x



114670

8x




104012

5x




102267

4x




100049

1x




153548
158568

2x




141251
141252

7x



1x



124400




2x

114290
114291



1




2




3




4




5




6




7




8




9




10




11




12




13




14





15




16









19




20







22




23




24





25




26




27







↓
28












29




30









32

